



Location	PCI Tweed Lake A-67	Date	2004-09-18	Report No.	1
Job Description	Field Inspection to Check Wellbore Integrity	AFE or Prop. Code		Amount	
Tubing pressure: 0 kPa Casing pressure: 0 kPa H2S conc. 0					

Travelled to location on Sahtu helicopter out of Norman Wells. Aerial inspection of location, okay. Found surface casing vent open. Performed 10 minute bubble test - no bubbles. Checked tubing and casing pressures, no surface pressures. Took several wellhead and location pictures. Installed new combination lock and recharged wellhead. Combo # 0246. Recorded wellhead component sizes and numbers. Made up wellhead diagram and detail report.

AFE # B934103 and B934101.

Daily Fluid:	Oil	m3	Lost	Recovered	Cum. Fluid:	Oil	m3	Lost	Recovered
			<input type="checkbox"/>	<input type="checkbox"/>				<input type="checkbox"/>	<input type="checkbox"/>
	Water	m3	<input type="checkbox"/>	<input type="checkbox"/>		Water	m3	<input type="checkbox"/>	<input type="checkbox"/>
Day cost	\$2,400	Cumulative cost	\$2,400	Supervisor	Victor Gascon				
Man hours	3	Cumulative man hours	3	Mobile number and area	cell 403 710-4968				