

| | | |
|--|---|--|
| Incident # | INC-2019-004-HUS-OA-2018-002 | |
| Incident occurred on: | February 13, 2019 | |
| OA/ACW #: | ACW-2018-003 | |
| Operator: | Husky Oil Ltd. | |
| Location: | Slater River – H-64 | |
| Summary of incident: | Spill- Freshwater with trace KCl (salt) | |
| Incident reported to OROGO by the operator on: | February 21, 2019 | |
| Incident reported to NT-NU Spill Line (if required) on: | February 13, 2019 | |
| Operator Follow-up Investigation Report: | Due: Mar. 6, 2019 Received: Mar. 8, 2019 | |
| Status: | <p>Feb. 13, 2019: Hose leak between tanks – 200L Spilled.</p> <p>Reported to Spill line and assigned number: 2019055.</p> <p>Feb. 21, 2019: OROGO Identified as lead agency under the NT/NU Spills Working Agreement.</p> <p>Husky had reported that it has been cleaned up.</p> <p>Mar. 6, 2019: Investigation report was not received.</p> <p>OROGO contacted Husky and requested the investigation report.</p> <p>Mar. 8, 2019: Follow up report received. OROGO is satisfied with the remediation – File Closed</p> | |
| Completed By: | Michael Martin – Safety Officer | |

This Report is subject to disclosure pursuant to paragraph 91(8)(h) of the *Petroleum Resources Act*.

If you would like this information in another official language, contact us at (867) 767-9097.