

Wend Lake M-47

Fri 85-02-22

8<sup>00</sup> AM  
Status

P.O.H with DST #5

1209-1216.5 m  
(Mount Clark)

P.F. WAB inc SAB

V.O. (4 hours)

- ( $\frac{1}{8}$ " choke) flow rate approx  $550 \text{ m}^3/\text{d}$  ( $19.2 \text{ mcf/d}$ )  
well head pressure gradually increasing
- ( $\frac{1}{4}$ " choke - last hour) flow rate approx  $800 \text{ m}^3$  ( $28.3 \text{ mcf}$ )
- flow rate too low to flow through separator
- no evidence of condensate at surface
- some formation damage is suspected

Expect to be out of the hole at NOON, DST report  
approx. 4<sup>00</sup> PM this afternoon.