

N E B C O P Y

Final Operational/Workover Report
Well Suspension
Paramount et al Liard M-25
Well ID #: 1867
UWI: 300M256030123305

On March 19, 2008 Paramount Resources Ltd. moved Concord Well Servicing rig # 101 onto Paramount et al Liard M-25 to suspend the well. Service rig operations were completed on March 25, 2008. A chronological summary of the suspension operations follows.

19/3/2008: Moved on and rigged up service rig.

20/3/2008: Finish rigging up service rig. Bleed casing and tubing to test vessel. Monitor casing and tubing while waiting on equipment.

21/3/2008: Removed the wellhead and installed the BOP's. While pressure testing BOP's the landing pupjoint collapsed. Wait on replacement pupjoint.

22/3/2008: Installed new landing joint and finished pressure testing BOP's. Unset the tubing hanger and pulled out of the hole with 213 joints of the 114 mm inside production tubing.

23/3/2008: Finished pulling the inner production tubing string. Install cross over for wireline lubricator.

24/3/2008: Rig in electric wireline unit. Found problem with wireliner's BOP's. Wait on replacement BOP's. Install and test replacement BOP's. Attempted to run in the hole with a 152.8 mm gauge ring. Got stuck in casing at surface. Pulled out of rope socket. Removed lubricator and retrieved gauge ring with rig winch. Ran 144.8 mm gauge ring to 3340 mKB.

25/3/2008: Ran and set a bridge plug at 3290 mKB. Filled hole with inhibited fresh water. Pressure tested the bridge plug to 6000 kPa. Dump bailed 8 linear meters of cement onto the bridge plug. Set a second bridge plug at 75 mKB. Removed the BOP's and installed the wellhead. Rigged out the service rig.