

Final Operational/Workover Report
Well Workover
Para et al Cameron H-03
Well ID # 1940
UWI: 300H036010117304

On February 24, 2007 Paramount Resources Ltd. moved Concord Well Servicing rig # 19 onto Para et al Cameron H-03 to perform a workover operation to establish the source of tubing leak and make repairs to correct the problem. Service rig operations were completed on February 27, 2007. A chronological summary of the operations follows.

- 24/2/2007:** Moved service rig onto location and rigged up service rig and ancillary equipment. Attempted to pressure test the tubing but leak detected. Unseated the bottom hole pump. Pumped 5 m³ water down the tubing. Pulled out of hole with the rod string and recovered the BHP. Reverse circulated with 32 m³ water. Recovered 3 m³ to test vessel.
- 25/2/2007:** Removed the wellhead and installed the BOP's. Rigged in Tuboscope inspection equipment. Picked up on tubing hanger and released tubing anchor. Pulled out of hole with tubing, inspecting tubing on the way out. Laid out 31 bad joints of tubing. Ran new tubing anchor on inspected tubing. Set tubing anchor with tubing bottom at 1433 mKB and landed tubing in tubing hanger.
- 26/2/2007:** Removed BOP's. While removing pupjoint from tubing string the tubing anchor sheared. Re-installed the BOP's. Pulled out of the hole with the tubing string. Re-dressed tubing anchor and re-ran on tubing. Re-set the anchor with tubing bottom at 1433 mKB. Removed the BOP's and landed the tubing in the tubing hanger. Installed the pumping wellhead.
- 27/2/2007:** Surface tested new BHP. Ran new BHP on original rod string. Filled the hole and pressure tested tubing to 7 MPa. Bled off pressure and stroke tested pump with rig to 5 MPa. Re-installed horses head and hung rod string in bridle. Rigged out service rig and ancillary equipment.



Paramount
resources ltd.

4700 Bankers Hall West, 888 3rd Street SW Calgary, Alberta, Canada T2P 5C5 www.paramountres.com

tel 403 290 3600 fax 403 262 7994

August 31, 2009

National Energy Board
5th Floor, 444 – 7 Avenue SW
Calgary, Alberta
T2P 0X8

Attention: Mr. Bharat Dixit, Chief Conservation Officer

Dear Sir,

Re: Request for Outstanding Reports for Paramount Wells

In response to your Request for Outstanding Reports for Paramount Wells to myself on March 9, 2009 and to Lloyd Doyle on June 9, 2009 Paramount offers the following. Please find enclosed the requested information for the remainder of the wells that were requested. Final Operational Reports are included for Cameron A-05, Bovie C-76A, Liard M-25, Fort Liard O-35 (two separate reports), Southeast Fort Liard N-01, Bovie F-66, Cameron C-74, Cameron H-03 (two separate reports), Cameron K-74, Liard 2M-25, Cameron 2F-73, Cameron L-73, Cameron J-04 (two separate reports), Cameron L-29, Cameron E-07, Cameron L-40, Cameron A-03, and Cameron E-72.

Should you require additional information on this application, please contact Dave Block at 206-3834 or fax 266-6032.

Yours truly,

Dave Block, P. Eng.
Engineering Consultant

2009 AUG 31 P 2:10
SALLE DE COURTE
NÉB/ONE