



File: WID #1476, 1555, 1600

24 October 2013

Bob Barvir
NAO Completions Superintendent
Suncor Energy E&P Partnership
150 – 6th Avenue SW
Calgary, AB T2P 3E3

Dear Mr. Barvir:

Suspended Wells Inspection Reports 2013
Tweed Lake M-47 (WID 1476)
Tweed Lake A-67 (WID 1555)
Canterra Bele O-35 (WID 1600)

Thank you for submitting the inspection reports for the above mentioned Wells. After reviewing, it is noted that Tweed Lake M-47 is showing a shut-in tubing pressure of 10.7 MPa. According to section 56 of the *Canada Oil and Gas Drilling and Production Regulations*, suspended wells require isolation from hydrocarbon and pressure zones. Please provide your plans for remedial and proper suspension of the M-47 well to the National Energy Board by 30 December, 2013.

Also, please continue to update us with future completions, abandonment plans and inspections of the suspended wells.

Should you require more information or have any questions please contact Saadat Javeed at 403-473-3782 or saadat.javeed@neb-one.gc.ca

Yours truly,

Iain Colquhoun
Acting Chief Conservation Officer