

Vicki Chan  
Vice President  
Alvarez & Marshal Canada Inc.  
1110, 250 – 6 AVE SW  
CALGARY AB T2P 3H7

September 30, 2020

Dear Vicki Chan:

**Compliance Status: Cameron B-38 Well – WID 2002 (OA-2018-003-SOG)**

On September 28, 2020, the Office of the Regulator of Oil and Gas Operations received a Well Inspection Report for the Cameron B-38 well (WID 2002) detailing the results of an inspection that was conducted on September 25, 2020. The report has been reviewed and confirms that the downhole barriers and the well head are still competent and operational.

Our records have been updated identifying the status of the well as suspended and in compliance with the Downhole Well Suspension Requirements (Section 5B) of the *Well Suspension and Abandonment Guidelines and Interpretation Notes* (Guidelines). Therefore, as indicated in Section 1 of the Guidelines, the Cameron B-38 well must be brought back into production or abandoned by January 31, 2023.

All operators must maintain and monitor suspended wells according to all requirements of the Guidelines and the *Oil and Gas Drilling and Production Regulations*.

Sincerely,



Pauline de Jong  
Executive Director

c. Orest Konowalchuk, Alvarez & Marshal Canada Inc.

Jayleen Robertson, ADM Planning and Coordination, Department of Lands

