





PETRO-CANADA
Petro-Canada Oil & Gas
WILDCAT HILLS WELLSITE

PCI TWEED LAKE
M-47

Emergency Phone: (403) 296-3000
1000' South of the Wellhead to the Point

TWEED LAKE M – 47

Site Investigation

Sept 18, 2013

Wellhead and area had no problems.

Wellhead valves were greased.

Casing was pressure tested.

Ground within 10 meters of wellhead was tested for gas migration, all readings from monitor were zero.

No immediate remedial action required.







Sump area is good, sump cap has settled, berm around sump is obvious.





Lease is very rocky, vegetative cover is good with grass, foxtail, alders and arctic willow.

Ungulates ie. moose and caribou as well as small mammals ie. fox and wolverines frequent the area.





