

DM 554208

WID: 2066 (B-09) and 2071 (2B-09)

B-09 was drilled to a depth of 392 m where 29 joints of surface casing were then ran. The driller attempted to remove the slips from the table and pulled too much on the casing causing the surface casing to come apart. It was then decided to abandon the well. Conductor and casing were cut off at ground level. The rig was then skidded over to 2B-09.

The drilling program and conditions attached with Para et al Cameron B-09 approval are applicable to Para et al Cameron 2B-09.

Contents of each well box:

<b>B-09 (2066)</b>	<b>2B-09 (2071)</b>
ADW application and forms	ADW forms
Well Termination Record	Well Termination Record
	Final Well Report
	Logs