

## WELLSITE SUMMARY INSPECTION REPORT

Well/Facility Name:	Fort Liard I-46	Operator:	Paramount Resources
Location of Inspection:	Ft. Liard South Field	Access method:	Road access through BC (Liard Highway KM 122)
Site Contractor:	N/A	Status:	Suspended
Approval Info	ACW-2016-005	WID:	1871
Date of Inspection	March 1, 2017	H2S Site:	No

### Summary of Inspection

<b>Activity on site</b>	Well Site cleared and snow covered		
<b>Conditions</b>	<b>Satisfactory (Y/N)</b>	<b>Comments</b>	
Site Access	Y		
Well Head Access	Y		
Well Signage	Y		
General Housekeeping	Y		
Other			

#### **Additional Site Hazards:**

Caution taken while driving on lease due to heavy snowfall.  
Site scheduled for snow clearing.

#### **Comments and Summary:**

Site operations idle, no work crew present.

#### **Documents Requested/ Collected:**

Photos taken

**Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.**

Mischa Malakoe S-002 / Brian Heppelle S-001

Inspected By

2017-03-09

Date Signed



Signature of OROGO Chief Safety Officer