

Incident #	INC-2019-007-HUS-OA-2018-002	
Incident occurred on:	February 21, 2019	
OA/ACW #:	ACW-2018-003	
Operator:	Husky Oil Ltd.	
Location:	Slater River – H-64	
Summary of incident:	Spill – Cement/Water Release	
Incident reported to OROGO by the operator on:	February 21, 2019	
Incident reported to NT-NU Spill Line (if required) on:	February 21, 2019	
Operator Follow-up Investigation Report:	Due: March 1, 2019 Received: March 9, 2019	
Status:	<p>Feb. 21, 2019: Cement waste bin end gate seal failed while being filled by vacuum truck.</p> <p>Reported to Spill line and assigned number: 2019071</p> <p>Husky reported it was cleaned up right away.</p> <p>Mar. 6, 2019: The Investigation report was not received on March 1, 2019.</p> <p>OROGO contacted Husky and requested the investigation report.</p> <p>Mar. 9, 2019: Follow up report received</p> <p>Corrective action and remediation meet OROGO's requirements – File Closed</p>	
Completed By:	Michael Martin – Safety Officer	

This Report is subject to disclosure pursuant to paragraph 91(8)(h) of the *Petroleum Resources Act*.

If you would like this information in another official language, contact us at (867) 767-9097.