

690-6-6-9



690-6-6-9

044.

PETROFINA CANADA LTD.

EXPLORATION - PRODUCTION
NINTH FLOOR, 736 EIGHTH AVENUE SOUTH WEST
CALGARY 2, ALBERTA, CANADA



Title of Report: Geophysical Survey Report

Company: Petrofina Canada Ltd.

Permits: 6332 - 6337

Area: Colville Lake

Location: 67°40'N, 126°00'W

Type of Survey: Seismic Vibroseis, 400% stack structure sections

Contractor: Sigma Explorations Ltd.

Sub-Contractor: Northern Geophysical Ltd.

Date of Survey: Winter of 1971 - 72

Contents:

- 1) Surface Elevation Map (3)
- 2) Base of Carbonate Map (3)
- 3) Near Basement Map (3)

E. W. Redmond

EWR:mb