

EDITED
EVENT ENHANCEMENT
STATICS
PLOT 09.061 09.51.29

This image appears to be a scan of a document or a photograph of a physical object, characterized by a dense, dark, and highly textured surface. The texture is irregular and noisy, with many small, light-colored specks and artifacts scattered throughout. The overall appearance is grainy and lacks clear definition, suggesting a low-quality scan or a very dark, textured surface. The image is framed by a thin, dark border, and there are some faint, horizontal lines visible near the top edge, possibly indicating the edge of the scanned area or the scanner bed.

```

#                                     #
# MUTE... MUTE OFFSET 000. 410. 415. 1210 METERS #
#                                     #
# MUTE TIME .000. .150. .300. .600 SECONDS #
#                                     #
# ***** PLOT PARAMETERS ***** #
#                                     #
# PLOT DIRECTION = RIGHT #
# PLOT AMPLITUDE = 3400 #
# THE X-Y TRAC = 00 #
#                                     #

```

Carolee O'S and Gas Lands
Administration
Administrations de pétrole et de gaz
des terres G. Carolee

DEC 19 1989

Enquiry - voir aussi Branch
Bibliothèque de l'Exploration des
Roches Sédimentaires

Project 2