



9211-E9-1-3 RE  
(was EXC O et al)

Date: May 28, 1991

AFE #: \_\_\_\_\_ AFE \$: \_\_\_\_\_ SERVICE CONTRACTOR: \_\_\_\_\_

TIME		PREVIOUS DAYS OPERATION	DAILY COST SUMMARY		
from	to	SISCP: _____ kPa SICP: _____ kPa SITP: _____ kPa	ITEM	#	\$
		Inspection, photo well head and lease.			
		SITP    0 KPa			
		SICP    0 KPa			
		Casing vent open, no blow.			
		Wellhead chained and locked with master No. 2126.			
		Well head requires Paramount sign.			
		1/2" valve for well head cap.			
		Lease requires clean up. Sawdust bags by well			
		head. Boards and pallets at west end of lease,			
		drilling line protruding from sump.			
			DAILY COST .....		
			PREVIOUS COST .....		
			CUMMULATIVE COST .....		
			DAILY RIG HOURS .....		
			CUMM. RIG HOURS .....		
			TOTAL LOAD FLUID .....		
			FLUID RECOVERED .....		
			FLUID LEFT TO RECOVER ...		
			NEW FLUID .....		
			ROADS: .....		
			WEATHER: ..		
			PHONE: .....		
			AREA: .....		
			REPORTED BY:     R. Campbell		
			REC'D BY: ..... P. Besler		

**BOP TESTS:** PRESSURE: YES / NO, \_\_\_\_\_ kPa FUNCTION: YES / NO