



WELL TERMINATION RECORD

This record is submitted in triplicate in compliance with Section 184 of the Canada Oil and Gas Drilling Regulations.

WELL DATA

Well Name: Paramount et al. Cameron I-74 Area: Cameron Hills, N.W.T.
Grid Area: 60° 10' 117° 15' Field/Pool:
Permit or Lease No.: SDL-009 Final Coordinates: Lat.: 60° 03' 35.977" Long: 117° 28' 19.197"
Drilling Unit: Phelps #4E Elevations: RT/KB: 782.62 m SX/GL: 777.77 m
Spud Date: 1994-01-27 @ 22:15 Rig Released: 1994-02-14 @ 12:00 Total Depth: 1644.00 m
PBTB 1465 m

CASING AND CEMENTING

O.D.:	Weight:	Grade:	Depth Set:	Cement and Additives:
244.5 mm	53.6 kg/m	J-55	396.00 m	30 T 0:1:0 Class G + 2% CaCl ₂
177.8 mm	34.2 kg/m	LS-65	1644.00 m	28.5 T 0:1:0 'G' + 33.3% Microsil + 0.5% T-10 + 9% CaCl ₂ and 20.0 T Thixmix G + 1% CA-2 + 0.4% D-23 + 0.10% SPC12000

PLUGGING PROGRAM

Approval of the following program was obtained by (person) from
(person) by means of
on 19

Type of Plug:	Interval:	Felt:	Cement and Additives:

Lost Circulation/Overpressure Zones: 165 m
Equipment left on Seafloor (Describe):
Provision for Re-entry (Describe and attach sketch):
Cores: Type: Conventional Intervals: 1407.00 to 1422.80 m, 1422.80 m to 1441.00 m
Other Downhole Completion/Suspension Equipment: See attached Completion Schematic.

CERTIFICATION

I certify on the basis of personal knowledge of operations undertaken at the above named well that the above information is accurate.

Signed: P. G. Besler P. Eng. Title: Assistant Drilling Manager
Name: P. G. Besler Date: June 8, 1994

Acknowledged by: Engineering Branch
Date: June 28, 1994

Well Status
Suspended ☒
Completed ☐
Abandoned ☐

File: 9211-P33-7-1
UWI 3001746010117150



RAPPORT DE CESSATION DE PUIITS

Ce rapport doit être présenté en trois exemplaires, conformément à l'article 184 du Règlement concernant le forage des puits de pétrole et de gaz naturel au Canada.

DONNÉES SUR LE PUIITS

Nom du puits: Région:
Étendue quadrillée: Champs/Gisement:
No. de Permis ou Concession: Coordonnées Finales: Lat: Long:
Unité de forage: Elevation-TR/GE: Fonds marins/sol:
Date du démarrage: Date de libération de l'appareil: Profond. Totale:

TUBAGE ET CIMENTATION

Diamètre extérieur:	Poids:	Qualité	Profondeur:	Ciment et Additifs:
.....				
.....				
.....				
.....				

PROGRAMME D'OBTURATION

L'approbation du programme de cessation fut obtenue par (personne)
de (personne)
par le 19

Type de bouchon:	Intervalle:	Profond. vérifiée:	Ciment et Additifs:
.....			
.....			
.....			
.....			
.....			

Zone de perte de circulation/surpression:

Équipements laissés sur les fonds marins (description):

Mesures prises pour la réintégration (description et schéma):

Carottes: Type: Intervalles:

Autre équipement en fond de trou pour l'achèvement/la suspension:

CERTIFICATION

Je certifie qu'à ma connaissance, les informations ci-haut mentionnées sont exactes.

Signé: Ing. Titre:

Nom: Date:

Reçu par:
Direction de la technique

État du puits
Suspendu ☐
Achevé ☐
Abandonné ☐

Date:

No. de dossier:

Canada