



WELL TERMINATION RECORD

This record is submitted in triplicate in compliance with Section 184 of the Canada Oil and Gas Drilling Regulations.

WELL DATA

Well Name: Paramount et al. Cameron B-25..... Area: Cameron Hills., NWT
Grid Area: 60° 10' N, 117° 30' W..... Field/Pool: Undefined
Permit or Lease No.: SDL 103..... Final Coordinates: Lat: 60° 4' 4.57"..... Long: 117° 34' 41.17"
Drilling Unit: Sierra #3..... Elevations: ~~DB~~ (KB) 757.7 m..... ~~SE~~ (GL) 754.3 m
Spud Date: 1990-03-20..... Rig Released: 1990-03-23..... Total Depth: 1649 mKB

CASING AND CEMENTING

O.D.:	Weight:	Grade:	Depth Set:	Cement and Additives:
244.5 mm	53.6 Kg/m	J-55	393.7 m	30t class 'G' + 2% CaCl ₂
139.7 mm	23.1 Kg/m	IK-55	1646.0 m	LITE Master + 0.1% DEF-2
				15t TEL Master + 1% Ca-2
				+ 0.15% DEF-3

PLUGGING PROGRAM

Approval of the following program was obtained by (person) Phil Christie..... from
(person) T M Baker..... by means of
letter..... on March 21..... 2000

Type of Plug:	Interval:	Felt:	Cement and Additives:

Lost Circulation/Overpressure Zones:

Equipment left on Seafloor (Describe):

Provision for Re-entry (Describe and attach sketch):

Cores: Type: Intervals:

Other Downhole Completion/Suspension Equipment: Well suspended 2000-03-23 as per attached workover report and bottomhole diagram.....

CERTIFICATION

I certify on the basis of personal knowledge of operations undertaken at the above named well that the above information is accurate.

Signed: Phil Christie..... P. Eng. Title: DRILLING MANAGER
Name: PHIL CHRISTIE..... Date: APRIL 4, 2000

Acknowledged by: T M Baker.....
Engineering Branch

Date: May 5/00
File: 9211-P33-4-6RE-WID-1756
UWI 3008256010117302

Well Status
Suspended ☒
Completed ☒
Abandoned ☐



RAPPORT DE CESSATION DE PUIITS

Ce rapport doit être présenté en trois exemplaires, conformément à l'article 184 du Règlement concernant le forage des puits de pétrole et de gaz naturel au Canada.

DONNÉES SUR LE PUIITS

Nom du puits: Région:
Étendue quadrillée: Champs/Gisement:
No. de Permis ou Concession: Coordonnées Finales: Lat: Long:
Unité de forage: Elevation-TR/GE: Fonds marins/sol:
Date du démarrage: Date de libération de l'appareil: Profond. Totale:

TUBAGE ET CIMENTATION

Diamètre extérieur:	Poids:	Qualité	Profondeur:	Ciment et Additifs:
.....				
.....				
.....				
.....				

PROGRAMME D'OBTURATION

L'approbation du programme de cessation fut obtenue par (personne)
de (personne)
par le 19

Type de bouchon:	Intervalle:	Profond. vérifiée:	Ciment et Additifs:
.....			
.....			
.....			
.....			
.....			
.....			

Zone de perte de circulation/surpression:

Équipements laissés sur les fonds marins (description):

Mesures prises pour la réintégration (description et schéma):

Carottes: Type: Intervalles:

Autre équipement en fond de trou pour l'achèvement/la suspension:


CERTIFICATION

Je certifie qu'à ma connaissance, les informations ci-haut mentionnées sont exactes.

Signé: Ing. Titre:

Nom: Date:

État du puits
Suspendu ☐
Achevé ☐
Abandonné ☐



Reçu par:
Direction de la technique

Date:

No. de dossier:

Canada