



WELL TERMINATION RECORD

This record is submitted in triplicate in compliance with Section 184 of the Canada Oil and Gas Drilling Regulations.

WELL DATA

Well Name: Paramount et al Cameron I-74 Area: Cameron Hills, NWT
Grid Area: 60° 10' N, 117° 15' W Field/Pool: Undefined
Permit or Lease No.: SDL 009 Final Coordinates: Lat: 60° 03' 35.977" Long: 117° 28' 19.197"
Drilling Unit: Phelps #4E Elevations: RTKB 782.62 m SEGL 777.77 m
Spud Date: 1994-01-27 Rig Released: 1994-02-14 Total Depth: 1644.0 mKB

CASING AND CEMENTING

O.D.:	Weight:	Grade:	Depth Set:	Cement and Additives:
244.5 mm	53.6 Kg/m	J-55	396.0 mKB	30t 'G' + 2% CaCl ₂
177.8 mm	34.7 Kg/m	LS-65	1644.0 mKB	'G' + 33.3% Microsil + 0.5% T-10 + 9% CaCl ₂ and 20t Thixmix + 1% CA-2 + 0.4% D-23 + 0.1% SPC12000

PLUGGING PROGRAM

Approval of the following program was obtained by (person) from
(person) by means of
on 19

Type of Plug:	Interval:	Felt:	Cement and Additives:

Lost Circulation/Overpressure Zones:

Equipment left on Seafloor (Describe):

Provision for Re-entry (Describe and attach sketch):

Cores: Type: Intervals:

Other Downhole Completion/Suspension Equipment: Well suspended 2000-03-24 as per the attached
servicing report and bottomhole diagram.

CERTIFICATION

I certify on the basis of personal knowledge of operations undertaken at the above named well that the above information is accurate.

Signed: Phil Christie P. Eng. Title: DRILLING MANAGER
Name: PHIL CHRISTIE Date: APRIL 4, 2000

Acknowledged by: J. M. Baker
Engineering Branch

Well Status
Suspended ☒
Completed ☒
Abandoned ☐

Date: May 5/00
File: 9211-233-7-1RE, WID 1792
UWI: 3001746010117150



RAPPORT DE CESSATION DE PUIITS

Ce rapport doit être présenté en trois exemplaires, conformément à l'article 184 du Règlement concernant le forage des puits de pétrole et de gaz naturel au Canada.

DONNÉES SUR LE PUIITS

Nom du puits: Région:
Étendue quadrillée: Champs/Gisement:
No. de Permis ou Concession: Coordonnées Finales: Lat: Long:
Unité de forage: Elevation-TR/GE: Fonds marins/sol:
Date du démarrage: Date de libération de l'appareil: Profond. Totale:

TUBAGE ET CIMENTATION

Diamètre extérieur:	Poids:	Qualité	Profondeur:	Ciment et Additifs:
.....				
.....				
.....				
.....				

PROGRAMME D'OBTURATION

L'approbation du programme de cessation fut obtenue par (personne)
de (personne)
par le 19

Type de bouchon:	Intervalle:	Profond. vérifiée:	Ciment et Additifs:
.....			
.....			
.....			
.....			
.....			

Zone de perte de circulation/surpression:

Équipements laissés sur les fonds marins (description):

Mesures prises pour la réintégration (description et schéma):

Carottes: Type: Intervalles:

Autre équipement en fond de trou pour l'achèvement/la suspension:

CERTIFICATION

Je certifie qu'à ma connaissance, les informations ci-haut mentionnées sont exactes.

Signé: Ing. Titre:


Nom: Date:

Reçu par: Direction de la technique

Date:

No. de dossier:

État du puits
Suspendu ☐
Achevé ☐
Abandonné ☐



Canada