



# APPROVAL TO ALTER CONDITION OF A WELL

This application is to be submitted to the Chief Conservation Officer at least 45 days before commencement of operations.

Well Name: Paramount et al Swede A-73 Area: Cameron Hills, NWT  
Operator: Paramount Resources Ltd. Contractor: Solid Production Services Ltd.  
Drilling Rig or Unit: N/A Depth: 1585m TD  
Coordinates: Lat: 60° 12' 09.48" N Long: 117° 43' 27.10" W  
Date ADW Issued: Jan. 26, 1990 Date of last Operation: March 26, 1990  
Elevation-KB/RT: 679.6m (ASL) GL/Seafloor: 675.56m

## TYPE OF OPERATION

Pull 'RZG' plug... Run static gradient... Flow test Sulphur Point...  
Upgrade wellhead.

## SUMMARY OF PROPOSED OPERATIONS

As per detailed program.

Signed: Dave Block  
Responsible Officer

Title: Engineering Consultant

Name: Dave Block

Company: Paramount Resources Ltd.

Date: Jan. 17, 2001

Phone: (403) 206-3834

## APPROVAL

An approved copy of this notice is to be posted at each wellsite.

Date: Feb 24/01

Signed: D. M. Baker

File: 9211-P33-5-1-RE

Chief Conservation Officer


WID: 1747  
UWI: 300A736020117302

## Well Status

Suspended ☒

Completed ☐

Abandoned ☐





# APPROVAL TO ALTER CONDITION OF A WELL

This application is to be submitted to the Chief Conservation Officer at least 45 days before commencement of operations.

Well Name: Paramount et al Swede A-73 Area: Cameron Hills, NWT  
Operator: Paramount Resources Ltd. Contractor: Solid Production Services Ltd.  
Drilling Rig or Unit: N/A Depth: 1585m TD  
Coordinates: Lat: 60° 12' 09.48" N Long: 117° 43' 27.10" W  
Date ADW Issued: Jan. 26, 1990 Date of last Operation: March 26, 1990  
Elevation-KB/RT: 679.6m (ASL) GL/Seafloor: 675.56m

## TYPE OF OPERATION

↑ Pull 'RZG' plug... Run static gradient... Flow test Sulphur Point...  
Upgrade wellhead

## SUMMARY OF PROPOSED OPERATIONS

As per detailed program

Signed: Dave Block Responsible Officer Title: Engineering Consultant  
Name: Dave Block Company: Paramount Resources Ltd.  
Date: Jan. 17, 2001 Phone: (403) 206-3834

## APPROVAL

An approved copy of this notice is to be posted at each wellsite.

Date: Feb 26/01 Signed: T. M. Baker  
File: 9211-P33-5-1RE Chief Conservation Officer

WID: 1747


UWI: 300A736020117302

Well Status

Suspended ☒

Completed ☐

Abandoned ☐



# APPROVAL TO ALTER CONDITION OF A WELL

***This application is to be submitted to the Chief Conservation Officer at least 45 days before commencement of operations.***

Well Name:	Paramount et al Swede A-73	Area:	Cameron Hills, NWT
Operator:	Paramount Resources Ltd.	Contractor:	Solid Production Services Ltd.
Drilling Rig or Unit:	N/A	Depth:	1585m TD
Coordinates:	Lat: 60° 12' 09.48" N	Long:	117° 43' 27.10" W
Date ADW Issued:	Jan. 26, 1990	Date of last Operation:	March 26, 1990
Elevation-KB/RT:	679.6m	(ASL)	GL/Seafloor: 675.56m

## TYPE OF OPERATION

Pull 'RZG' plug... Run static gradient... Flow test Sulphur Point...  
 ← Upgrade wellhead...

## SUMMARY OF PROPOSED OPERATIONS

. As. per. detailed. program. ....

Signed: Dave Block ..... Title: Engineering Consultant.....  
Responsible Officer  
Name: Dave Block ..... Company: Paramount Resources Ltd,.....  
Date: Jan. 17, 2001 ..... Phone: (403) 206-3834.....

## APPROVAL

**An approved copy of this notice is to be posted at each wellsite.**

Date: Feb 26/01 Signed: T. M. Baker

File: 9211-P33-5-1RE.....

WID: 1747

UWI: 300A736020117302

### Well Status

**Suspended** ☒ X

**Completed** ☒

Abandoned ☐

**Chief Conservation Officer**

