

Photo 1: Panoramic view of the lease facing south (August 18, 2005).



PARAMOUNT RESOURCES LTD.

Project FN-14130-CS.01	By SDE
File Plate 1	Date 2005/09/22

PHOTOPLATE #1  
O-80 WELLSITE



Photo 2: View of the remote sump area near O-80 (August 18, 2005).




Photo 3: View of the woody debris facing north (August 18, 2005).

 <b>ALPINE</b> ENVIRONMENTAL	Prepared for:	<b>PARAMOUNT RESOURCES LTD.</b>	
	Project FN-14130-CS.01	By SDE	
	File Plate 2	Date 2005/09/22	
	<b>PHOTOPLATES #2 AND #3 O-80 WELLSITE</b>		



Photo 4: View of the geotextile material facing east (August 18, 2005).



Prepared for:

**PARAMOUNT RESOURCES LTD.**

Project FN-14130-CS.01	By SDE
File Plate 2	Date 2005/09/22

**PHOTOPLATE #4  
O-80 WELLSITE**