

Husky Oil Operations Limited

707 8th Avenue S.W.
Box 6525, Station D
Calgary, Alberta, Canada
T2P 3G7

Bus: (403) 298-7273
Fax: (403) 750-1365

November 9, 2011

John McCarthy
Chief conservation Officer
National Energy Board
411 Seven Avenue SW
Calgary, Alberta T2P 0X8

MAIL ROOM
SALLE DE COURIER
2011 NOV - 9 P 12:56
WEB/ONE

RE: Well operations Report
Husky et al Stewart D-57

Dear Sir

Attached please find Well Operations Report documents for the well Husky et al Stewart D-57, which is in the Sahtu region of North West Territories. This operation report is for the cut and cap operation that took place on September 17th 2010.

The Well Operations Report Husky et al Stewart D-57 includes a well operations summary and before and after pictures. There were no fluid samples taken and no fluid analysis done

If you require anything else please do not hesitate to contact me at (403) 298-7273 or kim.richardson@huskyenergy.com

Best Regards,



Kim Richardson
Drilling Superintendent NWT
HUSKY OIL OPERATIONS LTD

Well Operations Report Well Operations Report for Stewart D-57

On September 17, 2010 cut and cap operations were conducted on Stewart D-57 as follows:

Held safety meeting regarding capping well.
Dug around wellhead for 1.5 meters deep to expose casing.
Cut windows in surface casing then cut the 2454.5mm & 177.8 mm intermediate strings.
Removed wellhead bowls except surface casing bowl with helicopter.
Tied helicopter to surface casing bowl & cut of bowl.
Cut all casing down 1.3 meters below ground level leaving the inner string 10 cm higher.
Capped inner string with cap. Cap has collar with 1/2 inch plug in welded to the top of the cap.
Installed donut rings around the 2 remaining strings.
Weld the sign & sign post to top of cap. Sign is 1.5 meters above ground level.
No fluid samples were taken

BEFORE



AFTER

