

WELLSITE SUMMARY INSPECTION REPORT

Well/Facility Name:	Bovie C76-A/ Ft. Liard	Operator:	Paramount Resources Ltd.
Location of Inspection:	Km 23.5 Paramount Bovie Winter Road Access	Access method:	Winter Road
Site Contractor:		Status:	Abandoned
Approval Info	OA-2018-004	WID:	1850
Date of Inspection	10/FEB/2020	H2S Site:	No

Summary of Inspection

Activity on site	Winter Road Access adjacent to abandoned well marker		
Conditions	Satisfactory (Y/N)	Comments	
Site Access	Y	Adjacent to Bovie Winter Road (Paramount) at km 23.5 (foot access 50m)	
Well Head Access	N/A		
Signage	Y	Sign is stable, erect and readable	
General Housekeeping	Y	Winter access, no signs of vegetative stress	
SCV Open and dead	N/A		

Additional Site Hazards:

Foot access, snow covered, trip/fall hazards.

Comments and Summary:

OROGO Inspection Team: Brian Heppelle (Chief Safety Officer) and Michael Martin (Safety Officer, Conservation Officer)
 Site snow covered, no apparent stress on visible vegetation. Sign is stable, erect and readable.
 Confirmed Long/Lat Coordinates of Well Sign (2020-02-10, 10:45 MDT): N 60° 15' 14.8" W 122° 59' 22.3"
 Well abandoned, cut/capped in March 2009

Documents Requested/ Collected:

Photos and notes taken on site.

Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.

Michael Martin S-004 / Brian Heppelle S-001

Inspected By

2020-02-26

Date Signed



Signature of OROGO Chief Safety Officer



Photo # 1: Abandoned Well Site – Adjacent to Bovie Winter Road; snow covered; no apparent signs of vegetative stress; sign is stable, erect and readable.



Photo # 2: Abandoned Well Site – Well Sign Bovie C-76A

