

SAMPLE DESCRIPTIONS

WELL ~~P.C.I. TWEED~~ P.C.I. CANTARA
TWEED LAKE

1

From	To	Descriptions
		Cement, silica cement, trace of anhydrite cement, poor to occasionally fair intercrystalline to fracture and wuggy porosity with minor thin veins of metasomatic chert: as above.
		MON: JAN 21 / 85
		Depth 231m
		STATUS TRIPPING FOR BIT
		Very little loss circulation encountered to date.